09/276346

COC

**PATENT** 

DOCKET NO.: 1999.06.003.BN0 CLIENT NO.: SAMS01-00130

Customer No.: 23990

OTPE 18006 W

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

in Mary 12 re U.S. Patent No. :

7,065,037 B1

Inventor(s)

Senthil K. Viswanathan et al.

Issued

June 20, 2006

Title

METHOD AND APPARATUS TO PROVIDE FACILITY AND

MODULE REDUNDANCY IN TELECOMMUNICATION

SWITCHING EQUIPMENT

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate

OCT 1 9 2006

of Correction

#### CERTIFICATE OF MAILING BY FIRST CLASS MAIL

Sir:

The undersigned hereby certifies that the following documents:

- 1. Request for Certificate of Correction (in duplicate);
- 2. Certificate of Correction (in duplicate); and
- 3. A postcard receipt

relating to the above application, were deposited as "First Class Mail" with the United States Postal Service, addressed to Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on October \_\_\_\_\_\_\_, 2006.

Date: 12,200

Date: 12 Oct. 2904

Mailer 11

John T. Mockler Reg. No. 39,775

P.O. Drawer 800889 Dallas, Texas 75380 Phone: (972) 628-3600 Fax: (972) 628-3616

E-mail: jmockler@munckbutrus.com

OCT 1 9 2006.

**PATENT** 

DOCKET NO.: 1999.06.003.BN0 CLIENT NO.: SAMS01-00130

O \ Customer No.: 23990

OCT 1 6 2006

### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.:

7,065,037 B1

Inventor(s)

Senthil K. Viswanathan et al.

Issued

June 20, 2006

Title

METHOD AND APPARATUS TO PROVIDE FACILITY AND

MODULE REDUNDANCY IN TELECOMMUNICATION

SWITCHING EQUIPMENT

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

#### REQUEST FOR CERTIFICATE OF CORRECTION

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

ATTORNEY DOCKET No.: 1999.06.003.BN0
PATENT No.: 7,065,037 B1

Respectfully submitted,

MUNCK BUTRUS, P.C.

Date: 12 Oct. 2006

John T. Mockler

Registration No. 39,775

P.O. Drawer 800889 Dallas, Texas 75380

Telephone: (972) 628-3600 Facsimile: (972) 628-3616

E-mail: jmockler@munckbutrus.com

# DUPLICATE

DOCKET NO.: 1999.06.003.BN0 PATENT

CLIENT NO.: SAMS01-00130 Customer No.: 23990

OCT 1 6 2006

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

nire U.S. Patent No. :

7,065,037 B1

Inventor(s)

Senthil K. Viswanathan et al.

Issued

June 20, 2006

Title

METHOD AND APPARATUS TO PROVIDE FACILITY AND

MODULE REDUNDANCY IN TELECOMMUNICATION

SWITCHING EQUIPMENT

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

#### REQUEST FOR CERTIFICATE OF CORRECTION

Certain clerical or typographical errors were noted in the above-identified patent as indicated on the attached Certificate of Correction.

Applicant respectfully requests that a Certificate of Correction be issued pursuant to 37 C.F.R. §1.322. It is believed that this error is the office's mistake and therefore no fee is due. If this is incorrect, the Commissioner is hereby authorized to charge any additional fee associated with this communication or credit any overpayment to Deposit Account Number 50-0208.

OCT 1 9 2006.

# DUPLICATE

ATTORNEY DOCKET No.: 1999.06.003.BN0

PATENT No.: 7,065,037 B1

Respectfully submitted,

MUNCK BUTRUS, P.C.

Date: 12 Oct. 2006

Jolan T. Mockler

Registration No. 39,775

P.O. Drawer 800889 Dallas, Texas 75380

Telephone: (972) 628-3600 Facsimile: (972) 628-3616

E-mail: jmockler@munckbutrus.com

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,065,037 B1

DATED

: June 20, 2006

INVENTOR(S): Senthil K. Viswanathan and Robert W. Cubbage

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 13, delete "5" after the term "SIU".

MAILING ADDRESS OF SENDER:

**Docket Clerk** 

P.O. Drawer 800889

Dallas, Texas 75380

PATENT NO. 7,065,037 B1

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.



Approved for use through 04/30/2007. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 7,065,037 B1

DATED

: June 20, 2006

INVENTOR(S): Senthil K. Viswanathan and Robert W. Cubbage

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 13, delete "5" after the term "SIU".

MAILING ADDRESS OF SENDER:

**Docket Clerk** 

P.O. Drawer 800889

Dallas, Texas 75380

PATENT NO. 7,065,037 B1

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria,

VA 22313-1450.